

**MARYLAND HISTORICAL TRUST
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes ☐
no ☒

Property Name: HA-2213: Bridge over a Tributary of Broad Creek Inventory Number: HA-2213
Address: Old Flintville Road over a tributary of Broad Creek adjacent to boat ramp Historic district: ☐ yes ☒ no
City: Darlington vic. Zip Code: 21034 County: Harford
USGS Quadrangle(s): Conowingo Dam
Property Owner: _____ Tax Account ID Number: _____
Tax Map Parcel Number(s): 31 Tax Map Number: 12
Project: Conowingo Hydroelectric Relicensing Project (FERC No. 405) Agency: Federal Energy Regulatory Commission
Agency Prepared By: TRC ENVIRONMENTAL, INC.
Preparer's Name: Ellen Jenkins Date Prepared: 10/10/2011
Documentation is presented in: HISTORIC STRUCTURES REPORT FOR THE CONOWINGO HYDROELECTRIC RELICENSING APPLICATION PROJECT
Preparer's Eligibility Recommendation: ☐ Eligibility recommended ☒ Eligibility not recommended
Criteria: ☐ A ☐ B ☐ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G
Complete if the property is a contributing or non-contributing resource to a NR district/property:
Name of the District/Property: _____
Inventory Number: _____ Eligible: ☐ yes ☐ no Listed: ☐ yes ☐ no
Site visit by MHT Staff ☐ yes ☒ no Name: _____ Date: _____

Description of Property and Justification: *(Please attach map and photo)*

Crossing a tributary of Broad Creek, the ca. 1850 two-span continuous wood deck bridge is supported on stone abutments and pier. The superstructure, probably a covered bridge design, has been removed and replaced with wooden decking remains on steel I-beams. Concrete blocks have been placed on the southern abutments for structural purposes.

NRHP Evaluation: Based on the information collected, TRC recommends the resource ineligible for the NRHP due to lack of integrity. Although relating to the early industrial history of the area, the demolition of the associated buildings as well as the rerouting of Flintville Road has compromised the integrity of association, setting, and feeling (Criteria A and B). Structurally the bridge's integrity of design, materials, and workmanship has been compromised by removal of the superstructure (Criterion C).

References:

Maryland Historical Trust (MHT)

2009 Standards and Guidelines for Architectural and Historical Investigations in Maryland. Crownsville,

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended ☐ Eligibility not recommended ☒

Criteria: ☐ A ☐ B ☐ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

MHT Comments:

Jonathan Sager
Reviewer, Office of Preservation Services

Bluntz
Reviewer, National Register Program

11/30/12

Date

11/29/12

Date

201204714

NR-ELIGIBILITY REVIEW FORM

HA-2213

HA-2213: Bridge over a Tributary of Broad Creek

Page 2

MD.

National Park Service (NPS)

1978 National Register Bulletin 24, Guidelines for Local Surveys: A Basis for Preservation Planning.
Washington, D.C. Revised 1985.

1990 How to Apply the National Register Criteria for Evaluation. National Register Bulletin 15, Washington,
D.C. Revised 2002.

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended _____

Eligibility not recommended _____

Criteria: ___ A ___ B ___ C ___ D Considerations: ___ A ___ B ___ C ___ D ___ E ___ F ___ G


MHT Comments:

Reviewer, Office of Preservation Services

Date

Reviewer, National Register Program

Date



HA-2213 Bridge over a Tributary of Broad Creek
 Conowingo Dam, 1995 USGS Topographic Quadrangle

MIHP Number: HA-2213

Resource Name: Bridge over a Tributary of Broad Creek

File Name	Description of View
HA-2213_2010-09-15_01.tif	Bridge and Piers, Looking Southeast
HA-2213_2010-09-15_02.tif	Bridge and Piers, Looking Southwest
HA-2213_2010-09-15_03.tif	Bridge Decking, Looking Northwest

Photos Printed with HP 100 gray photo cartridge on HP Premium Photo Paper (soft gloss)



HA-2213

Bridge over a Tributary of Broad Creek
Hartford, MD

E. Jenkins

9-15-2010

MD SHPO

Bridge and Piers, Looking Southeast

#1 of 3



HA-2213

Bridge over a Tributary of Broad Creek

Harford, MD

E. Jenkins

9-15-2010

MD SHPO

Bridge and Piers, Looking Southwest

2 of 3



HA-2213

Bridge over a Tributary of Broad Creek

Harford, MD

E. Jenkins

9-15-2010

MD SHPO

Bridge Decking, Looking Northwest

#3 of 3